

**THERMAL FITNESS OF CANADA'S
HOUSING STOCK: A THERMOGRAPHY/
PHOTOGRAPHY SURVEY**

Final report to:

**Jack Smith
Conservation and Renewable
Energy Branch
Energy, Mines & Resources,
Canada**

By:

**Scanada Consultants Limited
Oakville and Ottawa**

**Field Surveyors:
Thermoscan, St. John's
Enertek, Fredericton
Les Consultants en Conservation
de l'Energie, Montréal
ITA, London
Thermal Energy Consultants,
Winnipeg
Infraview and Surescan,
Vancouver and Victoria
and Infratech, Division of
Scanada**

September 27, 1982

**THERMAL FITNESS OF CANADA'S LOW-RISE HOUSING STOCK:
A THERMOGRAPHY / PHOTOGRAPHY SUMMARY**

EXECUTIVE SUMMARY

How many houses still have uninsulated walls or basements, how many are very air-leaky; are many poorly insulated; are many troubled by excessive moisture within the structure? Where are these "thermally unfit" units that represent the remaining potential market for "energy retrofit" programs, incentives, and strategies, public and private? What types, constructions and general conditions characterize this market across Canada?

Commissioned by Energy, Mines and Resources, seven teams of surveyors set out in March 1982 to help answer these questions - by scanning very broad samples of the housing stock by means of special street-level thermography/photography* traverses. Scanning the front and one end of each unit, the teams "captured" 13,788 units on film and video-thermography tapes. The traverses were laid out to criss-cross the neighborhoods of various ages throughout several Census Metropolitan Areas, the surveyors maintaining a balance of numbers within each age group representative of the region's stock.

Mild weather (which prevents clear thermography) caused only one structural gap in the commissioned survey: Vancouver could not be scanned at all. The teams reshuffled and added to their Western runs as well as possible, capturing the overall stock well beyond the contract stipulations:

- St. John's - 1,314 units, roughly balanced cross-section
- Fredericton/Moncton (as "one CMA") - 1,988 units, roughly balanced
- Montreal - 2,003 units, roughly balanced
- Hull - 374 units, roughly balanced

*Infra-red thermography, "heat picturing", is defined in note 2 following the report's Introduction.

- Toronto - 1,697 units, roughly balanced
- London - 2,081 units, roughly balanced
- Winnipeg - 2,008 units, roughly balanced
- Calgary - 744 units, generally balanced but some overrepresentation of recent stock, counterbalancing the Edmonton survey
- Edmonton - 984 units, generally balanced but some underrepresentation of recent stock

Plus further runs as weather and logistics permitted:

- Nelson - 77 units, almost all pre-1945
- Victoria - 56 units, almost entirely 1951-'60 bungalows
- Ottawa - 254 units, 41% pre-1945 and 59% post 1961.

The photo and video thermography record yielded these details, house by house:

- Age, Style, Type (and general condition is also assessable).
- Level of wall insulation - nil, medium, full.
- Completeness of insulation - voids or settlement.
- Basement insulation (very often obscured by snowbanks).
- Gable end insulation.
- Air leak locations and apparent extent.
- Presence of excessive moisture in wall.

The data base was compiled on computer and a preliminary analysis done. Although considerable re-weighting or normalization of numbers is feasible and desirable for better representativeness, the "first picturing" is indeed useful. Some primary results are tabulated in the Overall Data Summary Table, overleaf. Break-outs by age groups and CMA are presented in the report (Data Summary Tables), with a generous sampling of thermograms and photographs. The conclusions and recommendations comprise a summary report in themselves.



OVERALL DATA SUMMARY TABLE - 0's

	STYLE										TYPE					GENERAL LEVEL OF WALL INSUL.				COMPLETION OF INSUL.				AIR LEAKAGE				EXHAUSTION DR.	
	1 Storey	2 Storey	2-3 Storey	Split Level	Raised Bungalow	Single Detached	Semi Detached	Rov/Town	Duplex	Quadruplex	MOISTURE WALL	Nil	Med	Full	Settled	Poor Placement	Voids	Uniform	Low	Med	High	Basement	Attic						
FULL SURVEYS:																													
FIELD	34	4	32		6	24	78	15	4	2	26	5	25	70		1	4	96	10	59	31	41	N/A						
PRED/	37	20	16		12	4	93	5	1		5	4	60	36		7	4	89	67	30	3	18	N/A						
NOHL																													
MOHT	8	1	59		1	1	12	54	4	15	AR	50	32	17	3	1	1	96	69	19	12	9	N/A						
TOR	31	12	28		17	11	80	19	1		0	70	25	5				99	16	76	8	29	N/A						
LOWD	16	17	20		1	24	96	4			5	4	52	43		1	1	98	33	51	16		N/A						
WING	65	12	17		3	2	98		2		4	54	39	7		2	2	98	27	29	14	14	N/A						
CALG	55	11	14		9	11	94	5	1		0	2	50	48				100	16	79	4	1	N/A						
EDMN	62	26	4		1	7	98	2			0	9	52	39				98	36	56	8	0	N/A						
LIMITED SURVEY - NOT FULLY REPRESENTATIVE OF HOUSING STOCK:																													
HULL	46	14	35		1	5	92	4	3		12	1	44	55				100	60	38	2	44	N/A						
EXTREMELY LIMITED SURVEY - NOT REPRESENTATIVE OF HOUSING STOCK:																													
OTT		1	58				40	59	1		0	19	76	5				100	34	46	20	38	N/A						
NEL	17	12	41		8		100				0	42	49	9		1		99	20	80		20	N/A						
VICT	88					11	100				7	8	86	6	14	5	18	63	68	18	13	38	100						

Conclusions and Recommendations:

The survey method works well: street-level thermography/photography is indeed an effective survey tool that has, in the hands of seven teams,

- defined the present "thermal fitness" levels of the walls of 13,788 houses across Canada, in essentially one critical month before spring 1982. The use of double glazed windows as reference points ("self adjusting" on each house) has yielded an adequate definition of nil, medium and full insulation, with some apparent vagueness between medium and full. On all except some older stock (uninsulated) useful indications of air leakage character and degree were also captured. Presence or absence of basement insulation was revealed in those few cities free from snowbanks.
- delineated the pattern and extent of excessive accumulations of moisture within the walls of some recently built housing and older (retro-insulated) stock
- provided a permanent record of photographs and videotaped thermography that can be referenced and studied much further than in this "first picturing" report, in terms of thermal fitness, earlier or further validation and correlation with earlier or further on-site inspections or moisture probings, for example; and correlation with apparent general condition, regional attributes and socio-economic attributes. Since every unit is identified and traceable by street and number, apparently troubled units or puzzling units can now be selected from the survey and studied definitively in the field.

The thermography/photography interpretations have been formed into a computerized data base from which a rebalanced "first picture" of Canada's low-rise housing has been developed:

- About 18% (1.1 million) of the low-rise stock has completely uninsulated walls. More than half of these are in Toronto and Montreal, primarily solid masonry and plank frame respectively. (These are difficult but now economic to insulate. The remainder are wood frame, easy, safe and most economic to insulate.)
- About 42% or more are moderately insulated in the walls, while 40% or less are fully insulated. (It may be economically worthwhile to add further insulation within or on moderately insulated walls, i.e. presently having R7 or R8 (RSI 1.4) batts.
- Although foundations were hidden by snowbanks in many cities, those that were scanned suggest that only 22-33% of basements are insulated.
- While much of the insulated stock appears to be fairly airtight in the walls and wall-to-roof junctions, 50% appears to be moderately airleaky and 10% highly so.
- Regionally, peculiarities are apparent and significant. In addition to the distinct Toronto and Montreal uninsulated stock, half of Winnipeg's housing is uninsulated in the walls, probably due to the postwar sweep of double aluminum foil "insulation" in that region particularly. One third of St. John's newer housing appears to be significantly troubled with excessive moisture within the walls. (St. John's walls also appear more air leaky than generally observed elsewhere.) One tenth of older housing on both coasts appears to have similar accumulations, but this often appears to be due to rundown of water from attic condensation (and/or ice dams) in these older houses. Similar patterns were seen in older houses in Moncton/Fredericton, Hull and London, and in Winnipeg to a lesser extent. (Due to mild weather, it

was not possible to scan any newer houses on the West Coast; insulation and moisture questions there are left largely unanswered.)

Recommendations

The data base should be reviewed for maximum utilization, carrying out adequate validation and gap-filling where needed. For example, in no order of priority:

- Analysis and correlation of obvious retrofit insulation, and nil insulation, with wall and attic moisture problems.
- Follow-up scanning and field probes of moisture "flagged" houses in early winter to see if summer drying has taken place.
- Quick re-scanning of the several cities that were snow-blocked, especially to complete the picture of basement insulation.
- Analysis of data base, and field probing, to determine if there is indeed a strong correlation between excessive structural moisture and air leaky walls / raised basement houses / flueless houses / full insulation, in recently built stock especially on the coasts.
- Field probing of Winnipeg/Toronto/Montreal uninsulated stock: Is it primarily what the surveyors think it is?; Is it insulatable?
- Production of a basic Low-Rise Canada reference book delineating the stock (by age by region) in terms of physical and thermal condition - for public and private sector use.

- Revamping and updating the "Canada Model" approach to project quantifications of conserver measures, effects, costs, cost-benefits, resource demands, public and private sector policy opportunities.

**THERMAL FITNESS OF CANADA'S HOUSING STOCK:
A THERMOGRAPHY / PHOTOGRAPHY SURVEY**

Final Report to Jack Smith, Energy, Mines & Resources, Canada

From: Scanada Consultants Limited
Oakville and Ottawa, September 27, 1982

	Page
1. INTRODUCTION	1
With definitions, references and final scope.	
2. OVERVIEW OF METHOD Reference Appendix A.	4
2.1 FIELD SURVEY PROCEDURE	4
2.2 COMPUTER BASE STRUCTURE	6
2.2.1 Basic Data	6
2.2.2 Analysis Program	7
3. REGIONAL FINDINGS	8
3.1 THERMOGRAPHY / PHOTOGRAPHY COVERAGE:	8
TYPICAL EXAMPLES	
3.2 THERMOGRAPHY / PHOTOGRAPHY COVERAGE:	25
"THERMALLY UNFIT" EXAMPLES	
3.3 DATA SUMMARY TABLES	29
4. FIRST ANALYSIS OF FINDINGS	42
- OVERALL DATA SUMMARY TABLE	43
4.1 LIMITATIONS	42
4.1.1 Weather	42
4.1.2 Representing Whole CMA's	44
4.1.3 Air Leakage	45
4.1.4 Attic Insulation	45
4.1.5 Exterior Cladding Effects	46
4.2 FIRST ANALYSES	46
4.2.1 The Housing Stock	46
4.2.2 Thermal Fitness - Insulation	47
4.2.3 Thermal Fitness - Air Leakage	48
4.2.4 Moisture within the Walls	49
4.2.5 Low-Rise Canada: A First Picture	50
5. CONCLUSIONS AND RECOMMENDATIONS	53

**APPENDIX A: HOUSING THERMOGRAPHY / PHOTOGRAPHY SURVEY:
TECHNICAL GUIDELINES**

UNDER SEPARATE COVER: DATA CORRELATION TABLES

**THERMAL FITNESS OF CANADA'S HOUSING STOCK:
A THERMOGRAPHY/PHOTOGRAPHY SURVEY**

1.0 INTRODUCTION AND SCOPE

What is the present thermal condition of Canada's low-rise housing stock? What portion of this stock is insulated, and to what degree? How many houses still lack basement insulation, wall insulation, reasonable airtightness or double glazing? Are many insulated houses, new and old, plagued with excessive moisture in their insulation and structure, which can reduce both thermal fitness and useful life? What types, styles, ages, constructions and finishes characterize the low rise housing stock across Canada? How does "thermal fitness" appear to vary with these basic characteristics?

Answers to these questions would allow more meaningful analysis and accurate modelling¹ of Canada's housing energy realities, including estimation of the potential "market" for "energy retrofit". Costs of energy conservation and retrofit programs, including demands on material, labour, capital and energy resources, and potential savings as well as spin-off opportunities would become more reliably quantifiable. This knowledge of costs/benefits would allow better appreciation of the need for, scope and design of incentive programs, leverages, promotions and ventures. These answers would provide an information base of value to policymakers in both public and private sectors.

In February 1982 Energy, Mines and Resources Canada, as part of its research program to estimate the economic and technical potential for retrofit, initiated a Canada-wide, street level "Housing Thermography/ Photography Survey" to help create a data base answering many of these questions.² EMR called for an intensive effort to gather a comprehensive picture of the low-rise residential stock before the end of March 1982, since the survey would require ideal nighttime winter conditions for definitive

thermal scanning. The work required the use of nighttime video thermography as well as daytime photography, all in the short winter period from late February through March. At least seven Census Metropolitan Areas across Canada were to be surveyed. The survey concept involved the laying out of traverses in each CMA designed to cross-section older and newer neighborhoods representatively and thus "capture" each age group of houses adequately. Cold weather held until early April, allowing the successful picturing of 13,788 units.³

Obviously, the singular early priority was the set up and execution of a broad survey with maximum speed, so as to complete the picturing of the housing stock before winter's end. Once all the data was gathered and fully documented with complete identification (referenced always to specific street addresses) a second phase was carried out, transferring the whole data base to computer and then producing initial breakouts and correlations "as found" in terms of present or potential thermal concerns. The following information comprises a summary final report of the street level "Housing Thermography/ Photography Survey" of 13,788 Canadian residential housing units, and offers a technical profile and a first analysis of the housing thermal picture "as found" in 1982.

1. The construction of the current model, "Canada 2", required the use of some questionable data and tenuous guesses, as stated at the time. Because some of these inputs did err, this model appears to overstate present thermal quality (particularly, the extent of basement insulation), and hence understates potentials for upgrading. "Canada 2" is set out in: HEATING CANADIAN HOUSES: CURRENT PERFORMANCE AND POTENTIAL FOR IMPROVEMENT, prepared for Canada Mortgage and Housing Corporation by Scanada Consultants Limited, March 1979.
2. Thermography uses infrared photography to record apparent surface temperature distribution on thermograms, or "heat pictures". On a thermogram light shades indicate high radiation density which usually infers warmer temperatures; on the other hand, darker shades represent progressively colder temperatures. Careful interpretation of thermograms provides considerable information about a building's heat loss characteristics. Common building envelope defects, such as missing, poorly installed or wet insulation, or air leakage points, cause discernable surface temperature variations on floors, walls or ceilings.

Thermographic surveys can be carried out in three common modes: interior, aerial exterior, and street level exterior. Interior thermography is most definitive, but it has limitations for survey purposes. It requires resident cooperation, and time and costs on a nation-wide scale are prohibitive. Aerial thermography provides economical coverage of whole communities, but has very limited definition. It is eminently suitable for large flat roof areas, e.g. commercial-industrial-institutional. Street-level exterior thermography combines meaningful definition of walls and windows with great advantages of speed, unobtrusiveness and low cost, and is thus the favoured tool for broad surveying of housing.

3. The survey initially was intended to cover a target number of 2,000 housing units in each of the following areas: St. John's, Newfoundland; Fredericton/Moncton, New Brunswick; Montreal, Quebec; Toronto, Ontario; London, Ontario; Winnipeg, Manitoba; and Vancouver, British Columbia. Selected runs were called for in Ottawa, Ontario and Hull, Quebec to help provide better coverage of these two provinces.

It proved impossible, however, to survey Vancouver due to weather conditions. Therefore, to help represent Western Canada small runs in Victoria and Nelson, British Columbia, were substituted along with more substantial runs in Calgary and Edmonton, Alberta.

2.0 OVERVIEW OF METHOD

2.1 FIELD SURVEY PROCEDURE

In February 1982, Scanada Consultants Limited developed field survey procedures under the title "Housing Thermography/Photography Survey - Technical Guidelines and Specifications" and distributed these Guidelines to seven regional thermography contractors. The intent was to establish consistent scanning procedures and report formats for data collection and interpretation for the thermography surveys carried out across Canada during the months of February and March 1982. The Guidelines addressed the following areas: Preparation for Field Runs, Collection of Non-IR (non- infrared) Field Data, Collection of IR Field Data, and Weather Restrictions. Examples of Completed Route Maps and Completed Tables were included. (See Appendix A.)

These specifications were designed to help ensure consistent application of the video and 35 mm thermography. Just prior to the main work, several field trial runs established that double glazed windows could be used as a reliable temperature benchmark. When the infrared detector is set to record the window units at one level, the wall insulation levels and quality become consistently interpretable. Use of this benchmark, which is "self regulating" for each house, avoids errors due to thermostat setback or unheated rooms (which otherwise could have given a false "insulation" inference). The benchmark also ensures that thermography evaluation from Newfoundland to Victoria remains comparable. (The procedure is outlined under "Collection of IR Field Data" in Appendix A.)

To utilize the available night scanning time fully and permit quick drive-throughs, hard copy thermal records of each house were made as video tapes and 35 mm thermograms. During daytime, 35 mm colour slides or colour video tapes were taken of each house.

In the field, voice recording of comments on the video thermography tapes, and written tabulation of results and interpretations (Appendix A) allowed a maximum of data gathering and fresh interpretation in a minimum of time while permitting extensive follow-up and further verification. The tabulations were also designed for easy coding to computer. The field recordings and tabulations were verified later by Scanada by visual review of the thermographic and photographic records. (Video thermography records the infrared "signals" precisely as received and allows the viewer to replay and manipulate the image later just as if on site. For example, the display can be resolved to isotherms that help differentiate moisture from other anomalies.)

Prior to the field surveys, a meeting was held with each contractor in each region to review the guidelines and to examine the local conditions that might affect the survey. Assistance was given in obtaining maps and establishing the basic sampling approach of laying out random traverses that would capture numbers of houses proportional to the region's total stock in each age group. Daylight viewing and colour photography allowed all houses to be "aged" in the field, and verified later from the photo records, by knowledge of local styles, customs and materials. The thermography itself differentiated between constructions (e.g. balloon frame vs. platform frame) and this also helped in judging the age bracket.

The specifications defined the required weather conditions for the survey. In order to complete the last of the work, contractors were requested to take advantage of the best (coldest) available nights even if the ideal conditions were not occurring. Any variance from the outlined weather conditions was clearly documented so that it could be taken into account during the interpretations of the thermograms.

2.2 COMPUTER BASE STRUCTURE

2.2.1 Basic Data: The field survey was designed to determine and record these house characteristics:

1	Age
2	Style
3	Type
4	Moisture
5	General Level of Wall Insulation
6	Completion of Insulation
7	Air Leaks
8	Gable End Insulation
9	Basement Insulation
10	Attic Insulation

Through the use of the basic groupings, a computer useable data base format was developed to allow convenient data input and data management. To accomodate repetitive blocks of data, an input program was developed to allow rapid data entry and close verification. Then, two processes were used to check input data against the original raw data: 1. On-line error checking routines flagged any data that appeared suspect (such as a "post-'76 housing unit with no insulation") for further manual checking. 2. The complete data base printouts were randomly checked against the raw data tables, always checking at least one third of the data.

The Québec (Montréal) survey data revealed a common occurrence of 3-storey units. Since the program had no such category, these units have been recorded as 2½ storey units in the data base.

2.2.2 Analysis Program

The analysis program included all survey observations and yielded a full set of data correlations. It kept track of the total numbers of observations made, including houses with ambiguous or masked components. The program permitted analysis of any one correlation by any region. To reduce computer interface time, a "driving" routine was inserted into the basic data analysis package to allow "one shot" runs of the 23 listed correlations for each region.

In addition, the analysis package allowed for the setting of flags around "surprising" data to facilitate further verification and follow-up work. A list of the house codes and related "flag" descriptions can be produced for any regional data set.

3.0 REGIONAL FINDINGS

The seven thermographers surveyed the front and one end of each of 13,788 low-rise dwelling units across Canada. Thirteen characteristics were recorded and assessed on each, thus amassing more than 179,000 findings to form a picture of the housing stock in its present condition.

The findings have been tabulated first as Data Correlation Tables, which are voluminous and hence are presented under separate cover. The summary findings are presented here in two forms:

- example displays of thermograms and photographs judged to be:
 - a) typical of the housing in each region
 - b) representative of particular "problem cases".
- data summary tables.

Users are cautioned that all tabulations present the data "as found", with no attempt to normalize or rebalance the age groups to represent the CMA's actual pattern of housing more correctly. Each age group is probably well surveyed in itself but the overall inferences for each CMA should not be taken too literally without first normalizing the age patterns. This and other important limitations are set out in Section 4. FIRST ANALYSIS OF FINDINGS.

3.1 THERMOGRAPHY/PHOTOGRAPHY COVERAGE: TYPICAL EXAMPLES

The next 16 pages exhibit thermograms and photographs of houses judged to be typical of the existing stock and conditions in each region. Because of space limitations only one face is shown thermographically, although the front and one end, where viewable, were scanned, recorded and assessed for each house.



Scanada

3. 1 Examples of Regional Housing Units



Image # 1.0 House # S 1277
Location: St. John's Age: Pre '45
Style: 2-storey Type: Single Det.

Wall Insul: Med/Full Air Leakage: M
Comments: Note air leakage pattern at
base of dormer windows



Image # 2.0 House # S 1244
Location: St. John's Age: 45-50
Style: 1-storey Type: Single Det.

Wall Insul: Full Air Leakage: ---
Comments: Uninsulated basement,
crossbracing evident.




Image # 3.0 House # S 870
Location: St. John's Age: 51-60
Style: 1-storey Type: Single Det.

Wall Insul: Med Air Leakage: M
Comments: Uniform insulation placeme
uninsulated basement.



Scanada

3. 1 Examples of Regional Housing Units




Image # 4.0 House # S 945
 Location: St. John's Age: 51-60
 Style: 1-storey Type: Single Det.

Wall Insul: Full Air Leakage: Med
 Comments: Uniform insulation placement
uninsulated basement.




Image # 5.0 House # S 522
 Location: St. John's Age: 61-75
 Style: 1-storey Type: Single Det.

Wall Insul: Med Air Leakage: ---
 Comments: Flueless home, uniform wall
insulation.



Image # 6.0 House # S 559
 Location: St. John's Age: 76-82
 Style: 1 1/2-storey Type: Single Det.

Wall Insul: Full Air Leakage: Me
 Comments: Note air leakage at soffits
and around dormers.




Scanada

3. 1 Examples of Regional Housing Units




Image # 7.0 House # N 313
Location: Fredericton Age: Pre 45
Style: 2 1/2-storey Type: Single Det.



Wall Insul: Med Air Leakage: No
Comments: Uniform insulation placement
in walls.




Image # 8.0 House # N 898
Location: Fredericton Age: Pre 45
Style: 2-storey Type: Single Det.



Wall Insul: Med Air Leakage: ...
Comments: Minor insulation voids
with air leakage or moisture.



Image # 9.0 House # N 328
Location: Fredericton Age: 45-50
Style: 1 1/2-storey Type: Single Det.



Wall Insul: Med Air Leakage: Med
Comments: Note: Heat loss from attic
and framing details.




Scanada

3. 1 Examples of Regional Housing Units




Image # 10.0 House # N 1298
Location: Fredericton Age: 51-60
Style: 1½-storey Type: Single Det.



Wall Insul: Med Air Leakage: Med
Comments: Kneewall/roof area depicting heat loss.



Image # 11.0 House # N 1449
Location: Moncton Age: 61-75
Style: 1-storey Type: Single Det.



Wall Insul: Full Air Leakage: Low
Comments: Uniform wall insulation, uninsulated basement





Image # 12.0 House # N 985
Location: Fredericton Age: 76-82
Style: 1-storey Type: Single Det.



Wall Insul: Full Air Leakage: Low
Comments: Poor insulation placement, bel side window-uninsulated base



Scanada


3. 1 Examples of Regional Housing Units

Image # 13.0 House # 13 B 1
 Location: Montreal Age: Pre 45
 Style: 2-storey Type: Quadplex

Wall Insul: Med Air Leakage: Low
 Comments: Uniform wall temperature
Uninsulated basement - Note br.



Image # 14.0 House # 18 B 1
 Location: Montreal Age: Pre 45
 Style: 3-storey Type: Triplex

Wall Insul: Med Air Leakage: Low
 Comments: Note heat loss pattern in
attic and floor header




Image # 15.0 House # 30 B 1
 Location: Montreal Age: 45-50
 Style: 2-storey Type: Semi-det.

Wall Insul: Med Air Leakage: Med
 Comments: Air leakage, possible moistu
below sills.



Scanada

3. 1 Examples of Regional Housing Units




Image # 16.0 House # 2 C 1
Location: Montreal Age: 51-60
Style: 2-storey Type: Quadplex

Wall Insul: Med Air Leakage: Med
Comments: Air leakage, possible moisture below sills.




Image # 17.0 House # 5 C 1
Location: Montreal Age: 61-75
Style: 1-storey Type: Single Det.

Wall Insul: Med Air Leakage: Low
Comments: Minimal air leaks, under wall insulation.




Image # 18.0 House # 10 B 1
Location: Montreal Age: 76-82
Style: 2-storey Type: Row/Town

Wall Insul: Full Air Leakage: Low
Comments: 1st/2nd floor temperature diff due to emissivity difference



Scanada

3. 1 Examples of Regional Housing Units




Image # 19.0 House # T 632
Location: Toronto Age: Pre 45
Style: 2 $\frac{1}{2}$ -storey Type: Single Det.

Wall Insul: Nil Air Leakage: Med
Comments: Uninsulated solid masonry wall



Image # 20.0 House # T 860
Location: Toronto Age: Pre 45
Style: 2-storey Type: Single Det.

Wall Insul: Nil Air Leakage: Med
Comments: Uninsulated solid masonry wall




Image # 21.0 House # T 464
Location: Toronto Age: 45-50
Style: 1-storey Type: Single Det.

Wall Insul: Nil Air Leakage: Med
Comments: Uninsulated solid masonry wall



Scanada

3. 1 Examples of Regional Housing Units




Image # 22.0 House # T 179
Location: Toronto Age: 51-60
Style: 1 1/2-storey Type: Single Det.

Wall Insul: Nil Air Leakage: Med
Comments: Uninsulated solid masonry wall




Image # 23.0 House # T 52
Location: Toronto Age: 61-75
Style: 2-storey Type: Semi-det.

Wall Insul: Med Air Leakage: Med
Comments: 2nd floor uniformly med.





Image # 24.0 House # O 563
Location: Ottawa Age: 76-82
Style: 2-storey Type: Row/Town

Wall Insul: Full Air Leakage: Low
Comments: Heat loss from 1st/2nd floor header area



Scanada

3. 1 Examples of Regional Housing Units




Image # 25.0 House # L 464
Location: London Age: Pre 45
Style: 1.5-storey Type: Single Det.



Wall Insul: Nil Air Leakage: High
Comments: Similar wall/window temperature
Uninsulated, Brick veneer



Image # 26.0 House # L 469
Location: London Age: Pre 45
Style: 2-storey Type: Single Det.



Wall Insul: Full Air Leakage: Low
Comments: Some air leakage around
window frames



Image # 27.0 House # L 1123
Location: London Age: 45-50
Style: 2-storey Type: Single Det.



Wall Insul: Nil Air Leakage: Med
Comments: Note air leakage at
building jog.



Scanada

3. 1 Examples of Regional Housing Units



Image # 28.0 House # L 1316
Location: London Age: 51-60
Style: 1.5-storey Type: Single Det.



Wall Insuls: Nil Air Leakage: Med
Comments: Uninsulated - Note warm wall temperature





Image # 29.0 House # L 173
Location: London Age: 61-75
Style: Split-level Type: Single Det.



Wall Insuls: Med Air Leakage: Med
Comments: Thermal bridge visible through 2nd floor frame.





Image # 30.0 House # L 28
Location: London Age: 76-82
Style: Split-level Type: Single Det.




Wall Insuls: Full Air Leakage: Med
Comments: Framing pattern clearly evident. Insulation well placed.



Scanada

3. 1 Examples of Regional Housing Units


Image # 31.0 House # W 342
Location: Winnipeg Age: Pre 45
Style: 1-storey Type: Single Det.



Wall Insul: Nil Air Leakage: Med
Comments: Uninsulated stucco/frame
home.



Image # 32.0 House # W 581
Location: Winnipeg Age: Pre 45
Style: 1 1/2-storey Type: Single Det.



Wall Insul: Med Air Leakage: Med
Comments: Wall framing evident.
Foundation heat loss.



Image # 33.0 House # W 1445
Location: Winnipeg Age: 45-50
Style: 1-storey Type: Single Det.



Wall Insul: Nil Air Leakage: Med
Comments: Uninsulated stucco/frame home



Scanada

3. 1 Examples of Regional Housing Units




Image # 34.0 House # W 1723
Location: Winnipeg Age: 51-60
Style: 1-storey Type: Single Det.

Wall Insul: Med Air Leakage: Med
Comments: Insulation well placed
Basement uninsulated




Image # 35.0 House # W 814
Location: Winnipeg Age: 61-75
Style: 1-storey Type: Single Det.

Wall Insul: Med Air Leakage: Med
Comments: Uniform wall insulation
Basement uninsulated





Image # 36.0 House # W 851
Location: Winnipeg Age: 61-75
Style: Raised Rung Type: Single Det.

Wall Insul: Med Air Leakage: Low
Comments: Note: Heat loss from
1st floor header and foundation




Scanada

3. 1 Examples of Regional Housing Units



Image # 37.0 House # E 667
 Location: Edmonton Age: Pre 45
 Style: 1½-storey Type: Single Det.



Wall Insul: Med Air Leakage: Med
 Comments: Single glazing, storm door
 Uniform wall insulation





Image # 38.0 House # E 773
 Location: Edmonton Age: Pre 45
 Style: 1-storey Type: Single Det.



Wall Insul: Med Air Leakage: Med
 Comments: Single glazed picture
 Surface moisture in attic



Image # 39.0 House # E 158
 Location: Edmonton Age: 45-50
 Style: 1½-storey Type: Single Det.




Wall Insul: Med Air Leakage: Med
 Comments: Uniform wall insulation
 Uninsulated basement



Scanada

3. 1 Examples of Regional Housing Units


Image # 40.0 House # E 592
 Location: Edmonton Age: 45-50
 Style: 1-storey Type: Single Det.



Wall Insul: Med Air Leakage: Med
 Comments: Uniform wall temperature, St
Door, Basement uninsulated




Image # 41.0 House # E 181
 Location: Edmonton Age: 51-60
 Style: 1-storey Type: Single Det.



Wall Insul: Full Air Leakage: Med
 Comments: Air leakage at building
Probable single glazed



Image # 42.0 House # C 620
 Location: Calgary Age: Pre 45
 Style: 1-storey Type: Single Det.



Wall Insul: Nil Air Leakage: Med
 Comments: Wall framing evident
Single glazed windows



Scanada

3. 1 Examples of Regional Housing Units




Image # 43.0 House # C 581
Location: Calgary Age: 51-60
Style: 1-storey Type: Single Det.



Wall Insul: Med Air Leakage: Med
Comments: Basement uninsulated




Image # 44.0 House # C 121
Location: Calgary Age: 61-75
Style: 1-storey Type: Single Det.



Wall Insul: Med Air Leakage:
Comments: Uniform wall insulation
Foundation insulated



Image # 45.0 House # C 241
Location: Calgary Age: 61-75
Style: Raised Bungalow Type: Single Det.



Wall Insul: Full Air Leakage: Med
Comments: Uniform wall insulation



Scanada



3. 1 Examples of Regional Housing Units

Image # 46.0 House # C 501
 Location: Calgary Age: 76-82
 Style: Raised Bung. Type: Single Det.

Wall Insul: Full Air Leakage: Low
 Comments: New infill, foundation heat loss evident



Image # 47.0 House # V 51
 Location: Nelson Age: Pre 45
 Style: 1 1/2-storey Type: Single Det.

Wall Insul: Nil Air Leakage: Low
 Comments: Note single glazed w.




Image # 48.0 House # V 61
 Location: Nelson Age: Pre 45
 Style: 1-storey Type: Single Det.


Wall Insul: Nil Air Leakage: Medium
 Comments: Uninsulated stucco/frame home

3.2 THERMOGRAPHY/PHOTOGRAPHY COVERAGE: "THERMALLY UNFIT" EXAMPLES

Some example coverage of such cases is presented on the next three pages, representing the challenges (and opportunities) peculiar to each region. Included are:

- houses plagued with excessive moisture within the insulated wall structure, especially in Newfoundland;
- uninsulated solid masonry houses - difficult to retrofit with insulation - especially common in Toronto;
- examples of the surprisingly common incidence of completely uninsulated wood frame houses in Winnipeg;
- Calgary/Edmonton examples with single glazed windows and (common in all regions) completely uninsulated basements.

These are discussed in Section 4, FIRST ANALYSIS OF FINDINGS. The moisture phenomenon was found to some extent across Canada, and is given special consideration and analysis in a separate paper.






Image # 49.0 House # N 1018
Location: Fredericton Age: 61-75
Style: Raised Bung. Type: Single Det.

Wall Insul: Full Air Leakage: Lo
Comments: Moisture




Image # 50.0 House # S 1196
Location: St. John's Age: Pre 45
Style: 1-storey Type: Single Det.

Wall Insul: Med Air Leakage:
Comments: Moisture




Image # 51.0 House # S 1214
Location: St. John's Age: Pre 45
Style: 1.5-storey Type: Single Det.

Wall Insul: Med Air Leakage: Me
Comments: Uneven patterns of moisture



Scanada

3.2

THERMALLY UNFIT - UNINSULATED HOMES




Image # 52.0

House # T 456

Location: Toronto

Age: 45-50

Style: 1 1/2-storey

Type: Single Det.

Wall Insul: Nil

Air Leakage: Me

Comments: Uninsulated solid masonry w




Image # 53.0

House # T 1153

Location: Toronto


Age: 45-50

Style: 1-storey

Type: Single Det.

Wall Insul: Nil

Air Leakage:

Comments: Uninsulated solid masonry
may have hydronic radiators

AGA THERMOVISION®

Image # 54.0

House # W 155

Location: Winnipeg

Age: Pre 45

Style: 1 1/2-storey

Type: Single Det.

Wall Insul: Nil

Air Leakage: High

Comments: Uninsulated wood frame walls
stucco exterior



Scanada

3.2

THERMALLY UNFIT - UNINSULATED BASEMENT




Image # 55.0 House # C 115
 Location: Calgary Age: 61-75
 Style: 1-storey Type: Single Det.

Wall Insul: Full Air Leakage: Low
 Comments: Uninsulated basement




Image # 56.0 House # E 268
 Location: Edmonton Age: 45-50
 Style: 1 1/2-storey Type: Single Det.

Wall Insul: Med Air Leakage: Low
 Comments: Poor placement of insulation
likely due to framing





Image # 57.0 House # ---
 Location: Edmonton Age: Pre 45
 Style: 2-storey Type: Single Det.

Wall Insul: Med Air Leakage: Med
 Comments: Both images represent
insulation voids - poor placement

3.3 DATA SUMMARY TABLES



Seamless

DATA SUMMARY TABLES

Location: ST. JOHN'S

HOUSING STOCK CHARACTERISTICS BY AGE & CITY

AGE GROUP (% of Total)	STYLE										TYPE					GENERAL LEVEL OF WALL INSUL.					COMPLETION OF INSUL.					AIR LEAKAGE					INSULATION IN:
	1 Storey	1-1/2 Storey	2 Storey	2-1/2 Storey	Split Level	Refined Bungalow	Single Detached	Semi Detached	Row/Town	Duplex	Quadplex	NOISTUR WALL	Mid	Med	Full	Sectioned	Poor Placement	Voided	Uniform	Low	Med	High	Basement	Attic							
Pre 1940 15 %																															
1940-1950 7 %	10	9	69	1	12	60		25	15		19	21	47	32			4	96	2	66	32	1									
1951-1960 19 %	21	4	30		45	100					34	7	46	48			5	95	4	61	35	1									
1961-1975 40 %	60	15	23		2	1	94		6		16		31	69			2	7	91	21	60	19	10								
1976-1982 19 %	43		28		3	26	72	25	3	1	33	4	22	74			2	98	8	60	32	62									
TOTAL 100 %	14		20		22	44	82	2	7	9	22	1323	1255	100		1323	2	98	9	50	41	79	1104								
	No. of Homes Surveyed: 1314																														
34	4	32		6	24	78	15	4	2	26	5	25	70				1	4	96	10	59	31	41								



Location: FREDERICTON/MONCTON

too few basements visible because of snow drifts

DATA SUMMARY TABLES

Canada

DATE COUNTED (# of Total)	STILES					TYPE					GENERAL LEVEL OF WALL INSUL.				COMPLETION OF INSUL.					AIR LEAKAGE				INSULATION IN
	1 Storey	1-1/2 Storey	2 Storey	2-1/2 Storey	Split Level	Basement Bungalow	Single Detached	Semi Detached	Row/Town	Duplex	Quadruplex	MOISTURE WALL	W/L	Med	Pull	Settled	Poor Placement	Voids	Uniform	Low	Med	High	Basement Attic	
Pre 1945 342							2	98					94	5	1		1	1	98		71	16	13	50
8			33	67																				
1940-1950 102							6	94				1	5	33	62	27	1	1	71		74	14	12	31
2			97	3																				
1950-1960 222																								
8	2	4	64	31			11	13	60	4	12	25	82	17	1		2	98		63	10	27	2	
1960-1975 262																								
2	31		59	1	6	3	36	3	3	11	47			2	95	3			100	91	8	1		
1975-1982 102																								
2			99	2			1	19	74	1	7				100				100	22	78			
1982-1990 202																				1977				
2							1982					2008	2000			2008								
1990-2000 202																								
2	8	1	59	30	1	1	12	16	54	4	15	6	50	32	17	3	1	1	96	69	19	12	9	

primarily plank-frame
highly suspect-fooled by Lick veneer?
apparently transient wetting of brick under window sills

too few basements visible because of snow drifts

*Too few basements visible because of snow drifts



Location: _____

Location: _____

AGE GROUP (% of Total)	STYLE										TYPE							GENERAL LEVEL OF WALL INSUL.				COMPLETION OF INSUL.				AIR LEAKAGE				INSULATION DR.
	1-3 Storey										4-6 Storey							7-9 Storey				10-12 Storey				13-15 Storey				
	1 Storey	1-2 Storey	2 Storey	2-3 Storey	Spilt Level	Katand Bungalow	Single Detached	Row/Town	Duplex	Quadruplex	MODISTURE WALL	Nil	Had	Pull	Sealed	Roof Placement	Valde	Uniform	Low	Med	High	Seamenc	Acctic							
Pre 1945 27 %																														
8	24	20	54	1	1	94	6			32	2	55	43				100	47	51	2										
1945-1950 15 %																														
8	51	28	21		100				14	2	79	19					100	61	29	11	4									
1951-1960 8 %																														
8	25	61	14		100				7		25	75					100	75	25											
1961-1975 43 %																														
8	65	1	27	1	7	94	6			1		36	64				100	60	40		61									
1976-1982 7 %																														
8	26		56		19	56		44		4			100				100	93	7		100									
TOTAL 100 %	No. of House Surveyed: 374										362			374	373	374							104							
8	46	14	35	1	5	92	4	3		12	1	44	55				100	60	38	2	44									



Location: OTTAWA

AGE GROUP (% of Total)	STYLE										TYPE					GENERAL LEVEL OF WALL INSUL.				COMPLETION OF INSUL.					AIR LEAKAGE				ISOLATION IN:	
	1 Story	1-1/2 Story	2 Story	2-1/2 Story	Split Level	Raised Bungalow	Single Detached	Semi Detached	Row/Town	Duplex	Quadplex	MOISTURE WALL	MTL	Red	Full	Sealed	Foot Placement	Voids	Uniform	Low	Med	High	Basement	Attic						
Pre 1945 41 %																														
1	2	9	89			98			2			45	55				100	8	45	47										
1945-1950 0 %																														
1																														
1951-1960 0 %																														
1																														
1961-1975 50 %																														
1		100						100					99	1				100	56	43	1									
1976-1982 9 %																														
1		48	52					100					48	52				100	30	70										
TOTAL 100%	No. of Homes Surveyed: 254										254	253	254				253													
1	IGNORE TOTALS: SURVEY NOT A CROSS SECTION										SECTION																			
1	1	58	41			40		59	1		0	19	76	5			100	34	46	20										



Location: TORONTO

Location: FORNTO

[illegible]



Seamless

DATA SUMMARY TABLES

Location: LONDON

AGE GROUP (% of Total)	STYLE						TYPE					GENERAL LEVEL OF WALL INSUL.					COMPLETION OF INSUL.					AIR LEAKAGE					INSULATION IN	
	1 Story	2 Story	2-4 Story	SPIC Level	Entire Building	Single Detached	Semi Detached	Row/Town	Duplex	Quadplex	MOISTURE WALL	Nil	Had	Full	Sealed	Poor Placement	Unform	Low	Med	High	Basement *	Attic						
Pre 1940 31%	28	41	26	4		100					14	11	71	17		1	2	97	21	53	27							
1940-1970 8%																												
1970-1980 18%	50	38	8	4	100					4	6	72	23				100	53	39	8								
1980-1990 28%	52	3	18	25	2	100				2		49	61			1		99	63	35	2							
1990-2000 15%	35		13	51	2	100				1	2	58	41			1		99	26	61	14							
2000-2010 15%	29	3	32	34	2	78	22			1			100			1		99	27	54	19							
2010-2020 10%	36	17	20	1	24	1	96	4		2101	2097			2101			2100				116							
2020-2030 10%																												

*Too few basements visible because of snow



Saskatchewan

DATA SUMMARY TABLES

Location: WINNIPEG

AGE GROUP (# of Total)	STYLE						TYPE						GENERAL LEVEL OF WALL INSUL.				COMPLETION OF INSUL.					AIR LEAKAGE				INSULATION IN					
	1 Story	1-1/2 Story	2 Story	2-1/2 Story	Split Level	Related Bungalow	Single Detached	Semi Detached	Row/Town	Duplex	Quadplex	MOISTURE WALL	K11	Full	Sectioned	Poor Placement	Void	Uniform	Low	Med	High	Basement	Attic								
Pre 1945 36 %	44	24	24	8			98		2		4	87	13				4	96	7	78	15	2									
1945-1950 12 %																															
1951-1960 17 %	76	11	12				95		5		7	80	20				100			51	49	7									
1961-1975 26 %	93	3	1	2			100				2	59	40				1	99	24	69	7	15									
1976-1982 9 %	72	3	20		4	2	97		3		4	11	88				2	98	47	47	6	7									
Total 100 %	57	2	20	1	14	6	100				1	2052	2010	23	77		2	98	89	11	92										
	No. of Homes Surveyed: 2017										2008										2052					2010				2021	
	65	12	17	3	2	1	98		2		4	54	39	7			2	98	27	59	14	14									

*many of the 1945-55 "n11's" may have been "insulated" with the double aluminum foil of that time and region....essentially uninsulated.



Location: CALGARY

AGE GROUP (% of Total)	STYLE						TYPE						GENERAL LEVEL OF WALL INSUL.				COMPLETION OF INSUL.				AIR LEAKAGE				EXTRUCTION IN	
	1 Story	1-1/2 Story	2 Story	2-1/2 Story	Split Level	Radial Bungalow	Single Detached	Row/Town	Duplex	Quadraplex	NO. STUVE WALL	MIT	Had	FULL	Sealed	Foot Placement	Valde	Uplform	Low	Med	High	Maximum	Accto			
Pre 1945 26 %																										
1-45 11 %	58	31	6			5	96	3		1		5	56	40				100	34	63	4					
1945-1970 6 %	85	6	4		1	4	90	9		1		1	44	55				100	6	90	4					
1971-1980 51 %	84	2	7		5	2	100						51	49				100	9	88	2					
1981-1990 6 %	49	3	17		16	15	96	4				2	48	51				100	10	85	4	1				
TOTAL 100 %	10	8	48		4	29	74	21		4		2	48	50				100	15	75	10					
	No. of Homes Surveyed: 744												745	751	747	751		751		751		538				
1-00	55	11	14		9	11	94	4		1		0	2	50	48			100	16	79	4	1				



Location: EDMONTON

AGE GROUP (If not Total)	STYLE										TYPE										GENERAL LEVEL OF WALL INSUL.			COMPLETION OF INSUL.					AIR LEAKAGE			EMULATION DR.
	1 Storey	1-1/2 Storey	2 Storey	2-1/2 Storey	Split Level	Attached Bungalow	Single Detached	Semi Detached	Row/Town	Duplex	Quadruplex	MOISTURE WALL	Nil	Kad	Pull	Sealed	Foot Placement	Voided	Uniform	Low	Med	High	Basement	Attic								
Pre 1900 38 X																																
1900-1925 34 X												1	8	55	37		1	4	95	49	47	4										
2	60	34	1		5	100						6	55	34			1	99	31	60	8											
1926-1950 19 X																																
2	73	8	5		14	98	2					13	41	46			2	98	27	62	12											
1951-1975 7 X																																
2	65	3	5		6	21	91	9				18	54	28				100	15	63	22											
1976-1982 2 X																																
2	14	5	33		48	55	35		10			10	62	29				100	14	67	19											
TOTAL 1982	No. of House Surveyed: 984										985										986			987					983			
2	62	26	4	1	7	98	2				0	9	52	39			2	98	36	56	8	0										
																					987			987					673			
																					REPRESENTS SURVEY UNDER-			REPRESENTS NEVER HOUSING								

Location: VICTORIA

[illegible]

4.0 FIRST ANALYSIS OF FINDINGS

The Data Summary Tables of Section 3 are in turn summed up in a final table, overleaf. The first analysis of the findings should be undertaken with a clear appreciation of the limitations of the work (and the tabulations); these are now outlined.

4.1 LIMITATIONS

4.1.1 Weather

The late winter timing of the work was advantageous in one important respect: cases of condensation within the insulated walls were viewed at their worst, having had the whole of an unusually cold winter to accumulate. The disadvantages proved to be significant too:

- The limited time to carry out the survey (before mild spring temperatures prevented further thermography) did result in poorly-balanced cross-sectioning of some cities (refer to "normalization", next).
- Mild temperatures prohibited any surveying of Vancouver housing. (Victoria, with clear skies, did allow valid thermography on one night.) Some other areas had to be completed in slightly milder temperatures than stipulated, but the thermography was all done adequately.

Other winter effects detracted from the survey's coverage substantially. Abnormally generous snowfalls and drifts obscured the view of basements in very many cases. (In Victoria, the lush year-round vegetation severely curtailed the thermography run on the one cool night.) Unrelenting winds presented less-than-ideal thermography conditions in



Scanned

OVERALL DATA SUMMARY TABLE - 0'8

	STYLE										TYPE					GENERAL LEVEL OF WALL INSUL.					COMPLETION OF INSUL.					AIR LEAKAGE					UTILIZATION DR.	
	1 Storey	1-1/2 Storey	2 Storey	2-1/2 Storey	Split Level	Reared Bungalow	Single Detached	Semi Detached	Row/Town	Duplex	Quadruplex	MOISTURE WALL	Nil	Med	Full	Settled	Poor Placement	Voids	Uniform	Low	Med	High	Basement	Attic								
FULL SURVEYS:																																
NPLD	34	4	32		6	24	78		15	4	2	26	5	25	70		1	4	96	10	59	31	41	N/A								
PRED/	37	20	16	12	4	11	93	5		1		5	4	60	36		7	4	89	67	30	3	18	N/A								
MONC																																
MONT	8	1	59	30	1	1	12	16	54	4	15	4	50	32	17	3	1	1	96	69	19	12	9	N/A								
TOR	31	12	28	17	11	1	80	19	1			0	70	25	5		1	1	99	16	76	8	29	N/A								
LOND	36	17	20	1	24	1	96		4			5	4	52	43		1	1	98	33	51	16		N/A								
MINN	65	12	17	3	2	1	98			2		4	54	39	7			2	98	27	59	14	14	N/A								
CALG	55	11	14		9	11	94	5		1		0	2	50	48				100	16	79	4	1	N/A								
EDMN	62	26	4	1		7	98	2				0	9	52	39			2	98	36	56	8	0	N/A								
LIMITED SURVEY - NOT FULLY REPRESENTATIVE OF HOUSING STOCK:																																
HULL	46	14	15	1		5	92	4	3			12	1	44	55				100	60	18	2	44	N/A								
EXTREMELY LIMITED SURVEY - NOT REPRESENTATIVE OF HOUSING STOCK:																																
OTT	1	58	41				40		59	1		0	19	76	5				100	14	46	20	38	N/A								
MEL	17	12	41	8			100					0	42	49	9		1	1	99	20	80		20	N/A								
VICT	88				15		100					7	8	86	6	14	5	18	63	68	18	15	38	100								

Winnipeg and St. John's; the stipulated 25 kph limit had to be ignored some of the time. Such instances were recorded and the analysis of thermograms was conducted with wind effects in mind.

4.1.2 Representing Whole CMA's

Since the surveyors had to survey quickly on cold nights with no way to predict the final totals that could be surveyed, it was difficult to maintain a running cross-sectioning with the numbers of houses kept roughly proportional to the actual size of the age groups in each region. Further, the loss of Vancouver to its usual early spring resulted in contingency efforts to cover Victoria and Nelson where possible, and then Edmonton and Calgary, with less time for route mapping for complete cross-sectioning. With the exception of a few cities the surveyors did manage to capture fairly representative swaths of houses by age group. It is useful and arguably safe to take the findings as valid within each age group, but beyond that some normalization should be done first:

- When attempting to assess or picture the low-rise housing stock of a whole CMA, the age groups surveyed should first be weighted commensurately to represent the actual census numbers in each group. Since that has not yet been done, the "total" summations in Section 3's Data Summary Tables should be used cautiously, as rough inferences only, and likewise the whole of the overall Data Summary, this section.
- Any rigorous attempt to assess or picture the Canada low-rise stock must clearly be preceded by weighting of the (normalized) CMA's. The survey contract called for no such attempt; St. John's and Fredericton/Moncton areas each had the same number of houses surveyed as

Montreal or Toronto. There are indeed regional distinctions in the stock types and "thermal fitness", and the use of the combined CMA results as is would impute an overly Atlantic flavour to the whole country. (A "first picturing" of the whole country's stock, using a crude "normalization", is offered in section 4.2.5.)

4.1.3 Air Leakage

The thermographers, all familiar with low-rise housing, were asked to rate each case somewhat subjectively in terms of apparent air leakage. Scanada's further review of the thermography videotapes confirmed that this had been done consistently and usefully with the insulated stock everywhere. However, the uninsulated stock presents a "white on white" problem that makes the air leakage judgements rather tenuous and not always meaningful. (The outer wall surface is relatively warm because of little thermal resistance, therefore reading as light grey or white on the thermograms. Air leaks often dissipate through the uninsulated cavities, and in any case cause relatively little further warming, "white-on-white", which can only be interpreted by painstaking resolution of isotherms - and then not always clearly.)

4.1.4 Attic Insulation

Since the presence of attic insulation does reveal itself to outdoor thermography in many cases (attic vents showing cool, not warm), the surveyors were asked to attempt such observations on all cases. This attempt succeeded adequately in Quebec's flat roof cases (reading the soffit temperature indications) but not generally elsewhere.

4.1.5 Exterior Cladding Effects

Two claddings present difficulties in reading anything but gross thermal defects or general extent and amount of insulation in the wall. Brick veneer can be particularly obstructive, because of its thermal inertia (slight amounts of solar heat can be retained on the south and west walls through much of the night) and the relatively vented air space behind it. Aluminum siding is less obstructive, but it does diffuse its surface warm/cool boundaries because of its high conductivity as well as the slightly vented (but smaller) air spaces. These effects prevented adequate surveying of air leaks, voids and internal moisture in brick veneer houses, and sometimes reduced the clarity of moisture effects and air leaks under the aluminum. Only the brick veneer stock can be considered less than adequately surveyed, perhaps affecting London and especially Montreal (as noted on its Data Summary Table in Section 3).

4.2 FIRST ANALYSES

4.2.1 The Regional Housing Stock

The observed makeup of the low-rise stock presented no surprises; the types and styles of houses had been surveyed before (by low-altitude aerial photography, and analysis of urban fire maps and other records, for the Canada 2 model; ref. 1 following the INTRODUCTION). The recently built stock is indeed dominated by raised-basement "split entry" houses in the Atlantic and the West, and Newfoundland's older housing is also dominated by the earlier manifestation of raised basements. Such houses appear somewhat disposed to air leakage and attendant moisture problems, as will be discussed in a separate paper. In the Toronto and Montreal-Hull areas, all but the recent stock is distinguished by the

proliferation of solid masonry and plank frame houses respectively - both types usually being uninsulated and difficult (just economic) to insulate. Quebec also presents great numbers of two and even three-storey rows and duplexes with flat roofs. (As mentioned before, the 3's are listed as 2½'s to fit the prepared format.) Otherwise Canada's low-rise stock is of wood frame/full attic construction, eminently insulatable if not already well insulated.

Following a simple normalization exercise the quantities of each type and style could be defined rather well from this survey. If desired, the general condition of the houses and even some indications of socio-economic category could also be gleaned from the photographic survey, and correlated with extent of retrofit insulation, for example.

4.2.2 Thermal Fitness - Insulation

Even without normalization, several of the cities were cross-sectioned well enough to allow all results to be accepted as useful approximations. The extent and level of wall insulation is indicated as:

- St. John's: 5% nil, 25% medium level*, 70% full*
- Fredericton/Moncton: 4%, 60%, 36% respectively
- Montreal: 50% nil (plank frame, primarily ?), 32%, 17%
- Hull: 1%, 44%, 55%
- Toronto: 70% nil (solid masonry, primarily), 25%, 5%
- London: 4%, 52%, 43%
- Winnipeg: 54% nil (wood frame, double aluminum foil "insulation"?) 39%, 7%
- Edmonton: 9% nil (but the Edmonton survey under-represents newer houses), 52%, 39%

*"Medium" connotes generally the presence of the once-typical R7 and R8 batts (RSI 1.2 or 1.4). "Full" may connote the presence of R10 batts, or R12, in houses of the past decade and then the last few years (RSI 1.7, 2.1), or fully filled stud space yielding R14 or more (RSI 2.5) in retrofitted older houses.

- Calgary: 2%, 50%, 48% (but the Calgary survey over-represents new houses, intentionally counterbalancing this deficiency in the Edmonton survey)

Results from other cities should be taken as indicative only within the age groups covered.

The insulated houses generally appear uniformly insulated, with only 5% indicating missing batts or other substantial voids.

Basement insulation is now fairly common in St. John's, where 41% of the basements not obstructed by snow appeared insulated; Hull, 44%; and Toronto, 29%. The small sample of basements visible despite snowbanks in Fredericton/Moncton showed only an 18% incidence of insulation; likewise Montreal, 9%; London, 0%. The idea has scarcely caught on in the west: Winnipeg, 14%; Calgary and Edmonton essentially zero incidence of basement insulation (but newer housing is under-represented in the Edmonton survey).

4.2.3 Thermal Fitness - Air Leakage

Emphasizing again that uninsulated houses could not always be assessed reliably or consistently, it is useful to consider that 80% or more of the housing stock in almost all regions was judged to be exhibiting air leakage in the relatively low to medium ranges. Newfoundland stock was rated as 59% medium, 31% high - but much of the survey had to be done in breezy conditions which could bias the qualitative interpretations of the thermography. There were essentially no surprises - air leaks were prevalent at building corners, jogs, floor headers, partitions, party walls, and window and door framing. The judgements are qualitative, expressed from experience; "medium" does not mean "moderately good" any more than it means "typically bad".

4.2.4 Moisture within the Insulated Walls

One of the main objectives of the survey was to ascertain the incidence, intensity and inferences of the general nature of this problem. The survey coverage and findings do indeed allow this objective to be reached, but special analysis has proven necessary on a great number of houses.* This work is being completed for presentation in a separate paper. Pending that, the following summary of general findings is useful:

	Apparent excessive condensation within walls - age groups 1961-82 - not usually from attic	Likewise, older houses, mostly prewar and retro insulated. - apparently run- down from attic into walls in half of these cases
St. John's	22 - 33 %	16 % and up
Fredericton/Moncton and London	1 %	15 %
Winnipeg	1 %	4 %
Edmonton, Calgary (and Nelson prewar)	0 %	0%
Victoria - only 54 bungalows and raised basement houses surveyed, 1951-60.	- 11% 1951-60	-

A substantial fraction of the above wall moisture cases appears seriously wetted, conducive to rotting. In the separate paper under preparation, attempts are being made to assess the phenomena in the light of detailed field

*Video thermography can be "played with" in the office just as in field, allowing the resolution of isotherms that help distinguish between saturation effects and air leakage warming effects.

experiences in the past three years. In this survey the intent of identifying "flueless" (electrically heated) stock - most often associated with wall moisture problems - could not be met because of the common presence of chimneys for fireplaces and wood stoves. These could not yet be differentiated visually from combustion heated houses with active flues.

4.2.5 Low-Rise Canada: A First Picture

Using only the results from the fully-surveyed CMA's, with considerable prior knowledge of the stock, it is readily practicable to weight the survey results to project a very crude but useful "first picture" of the thermal fitness of the whole of urban low-rise housing in populated Canada.¹

Toronto and Montreal CMA's are taken to represent only themselves, since both have distinct masses of uninsulated (and difficult to insulate) low-rise stock: solid masonry in Toronto, plank frame in Montreal. Both also have substantial proportions of medium and high-rise housing, so their weightings are done² to reflect only their low-rise stock:

Toronto 8% of Canada low-rise
Montreal 9%
(Canada low-rise stock is taken as
6.1 million units)

The remainder of the country is represented by weighting by 1981 populations alone:

The other significant gaps in the survey are Eastern and Northern Ontario, Eastern Quebec, Quebec City and the Gaspé, Nova Scotia and The Territories. More rigorous normalization by age, region and urbanization could do better generally, and could utilize the partial runs too (Ottawa, Nelson, Victoria). Notwithstanding these caveats, the simple weightings given above can be used to project low-rise Canada as a whole:

Superstructure Insulation Level ⁴			Insulated Basements ⁵	Air Leakage (1945-1971 stock) ⁶		
Nil	Med	Full	Yes	Low	Med	High
18%	42%	40%	22-33%	40%	50%	10%

of low rise stock

Considering only the 18% (or 1.1 million) of the low-rise stock with no insulation in the walls, more than half of these are massed in Toronto and Montreal. The great majority of those in turn, and a significant minority of the others, are of solid masonry and plank frame construction - difficult but now economic to insulate.⁷

-
1. This simple exercise is entirely beyond the contract and is offered only as a useful indication, to be used with caution. A much more rigorous normalization of data is both feasible and desirable.
 2. Toronto and Montreal low-rise stock numbers are extracted and updated from Scanada's Canada 2, Ontario and Quebec models.
 3. Populations are taken from an undated "first copy.... newsletter" from Statistics Canada: "Canada Update from the 1981 Census".
 4. Delineation of "full" vs. "medium" insulation by thermography is not completely certain for recent stock.
 5. Insulated basements could not be scanned (because of snow banks generally, and shrubbery in Victoria) except in St. John's, Toronto, and the West, and in small portions of other CMA's. The evidence suggests that 30 to 40% of basements in central and eastern Canada are insulated, but only 5 to 10% of those in Western Canada: Thus 22 to 33% of Canada's house basements appear to be insulated at least above grade.
 6. Since thermography may not "see" air leakage clearly in the uninsulated housing, prewar housing was excluded from this tabulated assessment. To compensate, the generally tight post-1971 stock was also excluded. Refer also to LIMITATIONS.
 7. Economic application of insulations to such housing is detailed in "Insulating the Walls of Existing Masonry Houses", Scanada Consultants for Ontario Ministry of Housing and Ministry of Energy, March, 1981.

3.0 CONCLUSIONS AND RECOMMENDATIONS

The survey method works well: street-level thermography/photography is indeed an effective survey tool that has, in the hands of seven teams,

- defined the present "thermal fitness" levels of the walls of 13,788 houses across Canada, in essentially one critical month before spring 1982. The use of double glazed windows as reference points ("self adjusting" on each house) has yielded an adequate definition of nil, medium and full insulation, with some apparent vagueness between medium and full. On all except some older stock (uninsulated), useful indications of air leakage character and degree were also captured. Presence or absence of basement insulation was revealed in those few cities free from snowbanks.
- delineated the pattern and extent of excessive accumulations of moisture within the walls of some recently built housing and older (retro-insulated) stock
- provided a permanent record of photographs and videotaped thermography that can be referenced and studied much further than in this "first picturing" report, in terms of thermal fitness, validation and correlation with earlier or further on-site inspections or moisture probings, for example; and correlation with apparent general condition, regional attributes and socio-economic attributes. Since every unit is identified and traceable by street and number, apparently troubled units or puzzling units can now be selected from the survey and studied definitively in the field.

The thermography/photography interpretations have been formed into a computerized data base from which a rebalanced "first picture" of Canada's low-rise housing has been developed:

- About 18% (1.1 million) of the low-rise stock has completely uninsulated walls. More than half of these are in Toronto and Montreal, primarily solid masonry and plank frame respectively. (These are difficult but now economic to insulate. The remainder are wood frame, easy, safe and most economic to insulate.)
- About 42% or more are moderately insulated in the walls, while 40% or less are fully insulated. (It may be economically worthwhile to add further insulation within or on moderately insulated walls, i.e. presently having R7 or R8 (RSI 1.4) batts.
- Although foundations were hidden by snowbanks in many cities, those that were scanned suggest that only 22-33% of Canadian basements are insulated.
- While much of the insulated stock appears to be fairly airtight in the walls and wall-to-roof junctions, 50% appears to be moderately airleaky and 10% highly so.
- Regionally, peculiarities are apparent and significant. In addition to the distinct Toronto and Montreal uninsulated stock, half of Winnipeg's housing is uninsulated in the walls, probably due to the postwar sweep of double aluminum foil "insulation" in that region particularly. One third of St. John's newer housing appears to be significantly troubled with excessive moisture within the walls. (St. John's walls also appear more air leaky than generally observed elsewhere.) One tenth of older housing on both coasts appears to have similar accumulations, but this often appears to be due to rundown of water from attic condensation (and/or ice dams) in these older houses. Similar patterns were seen in older houses in Moncton/Fredericton, Hull and London, and in Winnipeg to a lesser extent. (Due to mild weather, it

was not possible to scan any newer houses on the West Coast; insulation and moisture questions there are left largely unanswered.)

Recommendations

The data base should be reviewed for maximum utilization, carrying out adequate validation and gap-filling where needed. For example, in no order of priority:

- Analysis and correlation of obvious retrofit insulation, and nil insulation, with wall and attic moisture problems.
- Follow-up scanning and field probes of moisture "flagged" houses in early winter to see if summer drying has taken place.
- Quick re-scanning of the several cities that were snow-blocked, especially to complete the picture of basement insulation.
- Analysis of data base, and field probing, to determine if there is indeed a strong correlation between excessive structural moisture and air leaky walls / raised basement houses / flueless houses / full insulation, in recently built stock especially on the coasts.
- Field probing of Winnipeg/Toronto/Montreal uninsulated stock: Is it primarily what the surveyors think it is?; Is it insulatable?
- Production of a basic Low-Rise Canada reference book - delineating the stock (by age by region) in terms of physical and thermal condition - for public and private sector use.

- Revamping and updating the "Canada Model" approach to project quantifications of conservation markets, measures, effects, costs, cost-benefits, resource demands, and public and private sector policy opportunities.

APPENDIX A

HOUSING THERMOGRAPHY/PHOTOGRAPHY SURVEY

Technical Guidelines and Specification

HOUSING THERMOGRAPHY/PHOTOGRAPHY SURVEY

Technical Guidelines And Specifications

1.0 INTRODUCTION:

The intent of these guidelines and specifications is to establish set procedures and formats to ensure regional consistency for the seven thermography studies carried out across Canada during the months of February and March 1982.

2.0 PREPARATION FOR FIELD RUNS:

As mentioned in previous letters from R.E. Platts, this survey requires some preliminary preparation to ensure that meaningful data is collected efficiently in the field. Much of this preliminary work should now be in process and the following information is included as further guidance and should ensure that all work is being produced in a similar manner:

2.1 CMA* Mapping By Residential Age Group

- A copy of A.E. LePage's "The Relocation Book 1981" is attached and should prove to be an excellent initial guide for establishing CMA residential age groups. In some cities more input will still be required from real estate agencies, planning departments and/or residents. In some cities the local CHIP office may have data that reflects house age by address.

- The age groups remain the same as indicated in the letter

* Census Metropolitan Area

should be in this category. Percentage breakdowns by age for each province in the survey have been calculated and are shown on the following table:

Newfoundland	21%	8%	21%	36%	14%
New Brunswick	35%	12%	12%	29%	12%
Quebec	33%	9%	19%	29%	10%
Ontario	33%	8%	19%	29%	11%
Manitoba	35%	10%	17%	28%	10%
Alberta	18%	9%	21%	34%	18%
British Columbia	21%	10%	18%	37%	14%

2.5 Identify Electrically Heated Housing*

The best contact to identify electrically heated houses in any CMA is the marketing division of the local Hydro. In most cases, the houses will be clustered in a neighbourhood and built by one builder. Contacting local builders may also help to identify the house. At least 100 electrically heated houses should be positively identified and included in the survey.*

2.6 Vehicle Preparation

During the preparation of your car or van ensure that it is well marked with slow moving vehicle reflective triangles, front and back. We have found a van to be preferable in areas of heavy snow to permit looking over the street snowbank.

* The field crews were unable to differentiate between combustion heated houses with active flues, and essentially flueless (electrically heated) houses having a flue for a fireplace and/or a wood stove. Therefore, this category on Table 2.0 has been ignored in all results and analyses.

of January 28, 1982;

A - Prewar (Pre 1945)

B - 1945 - 50

C - 1951 - 60

D - 1961 - 75

E - 1976 - 82

2.2 Maps

In Ontario the best source for maps is the Pathfinder Air Surveys Ltd. series of street maps. The maps contain all street names and include symbols to represent individual housing units.

For cities in other provinces, except the Maritimes, Military City Maps have been included, as these maps distinguish residential areas by shading.

Local planning offices should be contacted to determine if more suitable maps are available.

2.3 Tables

Tables have been prepared to tabulate most of the data required for the Thermography/Photography Survey. An original quality copy of each table has been included that will permit each company to have the desired number of copies made. The copies should be bound into some form of binder.

2.4 Proportioning Housing Stock Survey By Age

The Thermography/Photography survey should be designed to proportion the housing stock samples by age; i.e., if 12% of the CMA's housing stock is in the age bracket 1945 - 1950, then 12% of the total number of houses surveyed

3.2 Data Tables

Data tables have been set up to correlate with rolls of 20 exposure colour slide film. The first table correlates house numbers, video and photographic data to street addresses.

The second table records the pertinent thermography survey information and initial interpretation of the thermographic survey.

Table 1.0

Location	
Sheet No.	
House #	
Std. Photo Date	Roll #
	Slide #
Address	

Table 2.0

Location
Sheet No.
House #
Age
Style
Type
Moisture

3.3 Standard Colour Slides

One normal daytime colour slide is required for each house included in the survey.

- Suggested film type

20 Exp. Colour Slide Film ASA100

(such as Photo King 135-20 @ \$3.99 ea. incl. processing).

3.0 COLLECTION OF NON-IR FIELD DATA:

If time permits, it is preferable to collect the data outlined in this section prior to the IR scans. Non-IR Field Data could be collected by a different crew during the day prior to the evening thermographic survey.

3.1 Maps

The inspection route should be clearly mapped out prior to the IR scan. An overlay transparency should be used to identify items such as house numbers and side of street scanned. Refer to Attachment A which shows an example of a completed map.

It is important at this stage to clearly allocate house numbers to specific units. The house number shall be assigned on the following basis. Preceding each house number there must be a letter that represents the CMA.

St. John's	-	S	
Moncton	-	N -	New Brunswick
Fredericton	-	N -	
Montreal	-	M	
Ottawa/Hull	-	O	
Toronto	-	T	
London	-	L	
Winnipeg	-	W	
Edmonton	-	E	
Calgary	-	C	
Nelson/Victoria/			
Vancouver	-	V	

e.g. T215, T216, T217, etc.


Then, the units should be numbered consecutively from start to finish.

Scanada Consultants Limited



Project			By D. S. Lenahan	Page
Job No. S.8218	Job Title HOUSING	Date Feb. 15, 1982		of
THERMOGRAPHY SURVEY				

Diagram 1.0 - ORIENTATION OF PHOTOGRAPHIC AND THERMOGRAPHIC SURV



- The 1st slide on each roll should shown the first house of the roll and include a person standing in the photo holding a number to represent the roll number.
- Each slide to be clearly marked with house number.
- Refer to diagram 1.0 which shows the intended orientation of the slide.
- Slides are to be submitted to Scanada in slide cube containers that hold 40 slides per cube. These cubes should be suitable for use in a Bell & Howell Cube Slide Projector.

4.0 COLLECTION OF IR FIELD DATA:*

4.1 Video Tapes

The infrared video tapes should be produced according to the following guidelines:

- The scanning sequence should include a clear steady view of one side and the front of each house. Refer to diagram 1.0 which shows the intended orientation of the scanning.
- Each view should be held steady for at least a count of 5 to permit thermograms to be produced from the video tape.
- The vehicle speed will be 5 mph or less to ensure steady IR images.

*Equipment in all cases shall be AGA Thermovision Model 750 or successive models.

- The vehicle should be fully stopped when a thermogram is taken to ensure a crisp image.
- Each slide should be clearly marked with the house number.

Note: For companies that are not recording IR data on video tape at least 2 - 35 mm slide thermograms are required for each house inspected. These slides shall be labelled as follows: L 382 A and L 382 B to designate A and B views of house number 382 in London.

4.3 Completion of Table 1.0 and Table 2.0

Table 1.0 and Table 2.0 must be completed during the collection of the infrared images.

Information that is required to complete Table 1.0 is as follows:

Date:

IR Video Data

Tape #

Counter #

IR Photo Data

Roll #

Slide #

Time:

Weather:

Socio-Economic Characteristics:

Information that is required to complete Table 2.0 is as follows:

Date:

Moisture: Moisture Signs in Walls

- indicate if moisture signs appear to be present.

- In order to ensure regional consistency in the thermography scanning and interpretation, sealed double glazed or double windows shall be used as a benchmark. Adjust the level with the isotherm set at .70 to highlight the window glazing on the lee side of the structure. In Toronto at -10.7°C Range 2 was used. If the level is moved from this setting during the scanning to "look at" other details this change should be noted on the voice trace of the video and returned to the normal setting prior to scanning the next house.
- At the start of each new video tape the tape counter must be reset to zero.
- Label each video tape with the following information:

Company Name

CMA Name

CMA District

Tape Number

House # _____ To House # _____

- All conversations/comments made during the infrared scan should be recorded on the video tape.

4.2 IR 35mm Slides

It will be necessary to take 35mm slide thermograms during the field survey to represent a typical housing unit in each neighbourhood. Thermograms that represent examples of defective units should also be taken. The following guidelines should be followed:

- Recommended film type

Kodak Ektachrome ASA400 ER 135-36 Exp.

(Polaroid not acceptable)

- | | |
|----------------|------------------------------------|
| Thermographer: | - Operate AGA system |
| | - Call out house characteristics |
| Data Recorder: | - Operate video system |
| | - Complete Table 1.0 and Table 2.0 |

5.0 WEATHER RESTRICTIONS:

As a specific guide, the ASTM Draft Standard should be reviewed.

In general, the following guidelines should be followed for this survey:

- Ensure that the exterior surfaces of the buildings are dry, i.e., do not scan during or a short time after precipitation.
- Wind speed should be 15 mph or less.
- Temperature difference between indoor and outdoor air should be at least 15°C. It is preferable that the exterior air temperature be below 0°C.
- The inspections should be done at night to eliminate direct solar gain problems. In light frame houses, it generally takes 2 hours for the exterior to cool down. In heavier construction, e.g., solid masonry, it may take as many as 8 hours to dissipate the direct solar gain.

Weather data should be clearly tabulated during the infrared inspection and for 3 days prior to the inspections. The following information should be included:

General Level of Wall Insulation: Nil, Med., Full

- mark the category that best describes the house.

Nil - no sign of insulation present

Med. - moderate levels of insulation, say R8 batts

Full - house has substantial insulation present, say R12 - R20 +

Completion of Insulation: I Void

- state a I of the walls that contains voids

Air Levels: Low, Med., High

- identify the air leakage level

Insulation: Attic, Gable End (in 1½-storey only),
Basement

- if this information can be determined, the presence of insulation in these areas should be identified with a check (✓) mark. If insulation is definitely not present, indicate this with an ("X").

During the completion of these tables, the microphone for the video should be left on and any other comments should be read into the tape.

4.4 Suggested Personnel

Based on trial runs, it appears that the following crew is required to effectively record the information during the infrared survey.

Driver:

- Drive the vehicle
- Verify numbers
- Indicate house numbers to the thermographer
- Clearly map out the route followed

Attachment A

Map Example

Technical Guidelines and Specifications

Temperature (maximum and minimum)

Wind Speed

Wind Direction

Relative Humidity

Precipitation

Cloud Cover

6.0 TRANSFER OF FINDINGS:

At the completion of the Thermography/Photography survey, the following information is to be forwarded to myself:

David W. Bailey, P. Eng.,
Scanada Consultants Ltd.,
446 Reynolds Street,
Oakville, Ontario.
L6J 3M4

The data is to be in the following format:

Maps:	Shall be identified as outlined in Attachment A.
Video Tapes:	Original tapes labelled as described in Section 4.1.
IT Slides:	Original slides, clearly labelled with house numbers in labelled slide cubes.
Daytime Slides:	Original slides, clearly labelled with house numbers in labelled slide cubes.
Tables:	Table 1.0 and Table 2.0 are to be completed and in a format suitable for Xerox reproduction. Refer to Attachment B which shows examples of completed tables.



Project	Attachment A		By	DSL	Page
	Map Example		Date	Feb. 15, 1982.	of
Job No	S.8218	Job Title	Housing	Thermography Survey	



Attachment B

Examples Of Completed Tables

Technical Guidelines and Specification



Scanned

Table 1.0

THERMOGRAPHY SURVEY

Locations:

Toronto

Date: Feb 15, 1982

Sheet No.: 1A

HOUSE #	IR VIDEO DATA		IR PHOTO DATA		STD. PHOTO DATA		ADDRESS
	Tape #	Counter #	Roll #	Slide #	Roll #	Slide #	
T 1	1.	001	1	1	1	1	25 Parkwood Dr
2		005					27
3		011					29
4		014					31
5		021					33
6		026					35
7		029					37
8		035					39
9		042					41
T 10		052					43
T 11		051					45
2		058					47
3		063	1	2			10 Lakeview Cres.
4		074					12
5		091					14
6		099					16
7		105					18
8		110					20
9		121					22
20		128					24

Comments: (Time, weather, socio-economic characteristics, etc.)

Feb 15/82 11:00 PM

Parkwood: Solid Masonry house, clear sky, No Precip. Wind Nil, Temp -10.7°C

1A

[illegible]

POOR

QUALITY

ORIGINAL